




Mounting to a hard below ground level surface.




1) Attach a 40 cm extension to each leg of the device.



2) Place the device on a solid foundation - the foundation must be 40 cm below ground level.



3) Attach the device to the foundation - use 4 M14x100 expansion bolts.



4) Backfill the mounting location and level the surface.